


**NEEDHAM RANCH ARCH**

**Power Lines Above  
Not Shown**







No Spread Footing, Only Spot Footing



No Bond Beam Between Columns







Existing Electrical Conduit

Drop Catch Basin?



Fiber Optic Conduit Inside  
Existing Abandon Oil Line







Fiber Optic Line



Rock Pocket Spawl







Edge of Spot Footing

Existing Conduit